

To: Rodriguez, Dante[Rodriguez.Dante@epa.gov]; Jeryl Gardner[JGARDNER@ndep.nv.gov]
Cc: Seter, David[Seter.David@epa.gov]; Mattucci, Rich (BROWN & CALDWELL)[RMattucci@brwnald.com]; Zimmerman, Chuck[CZimmerman@brwnald.com]; John Batchelder[jbatchelder@envirosolve.com]
From: Oman, Jack
Sent: Fri 7/24/2015 7:13:53 PM
Subject: FW: FMS Hydraulic Test Update
FMS Hydraulic Test Progress - 072415.pdf

.....
>>>>>>

Dante and Jeryl,

This email summarizes the status of the hydraulic testing we are conducting at the Yerington site.

Please let Rich or myself know if you have any questions or would like to discuss.

Thanks,

-jack

From: Mattucci, Richard [mailto:RMattucci@brwnald.com]
Sent: Friday, July 24, 2015 10:11 AM
To: Oman, Jack; jbatchelder@envirosolve.com
Cc: Zimmerman, Chuck; Hyatt, Ron; Gupta, Alok
Subject: ARC: FMS Hydraulic Test Update

Jack and John

The attached table summarizes our progress on the hydraulic test through today. We reached the operational suction head limit with the Godwin Pump at the 8 foot level in the VLT Pond. We are switching the pumps around to transfer fluid from the C Pond to continue filling the B Pond on Monday. The B Pond staff gauge level is about 5.25 feet just below the level we anticipate finding the leak and the B pond surface is free of salt.

Richard Mattucci
Brown and Caldwell
RMattucci@brwnald.com
T 775.283.0809 | C 775.315.4697

